

Important: Read all instructions prior to installation.

XSX Series

NSF Certified Washdown UFO High Bay



XSX-HBDU100W-50KSV-DNCB

Safety and Notes



- Product should be installed and serviced by a certified electrician in accordance with applicable national, state, and local building and electrical codes.
- To reduce the risk of electric shock, ensure that the main power source and circuit breakers are switched off before performing any installation or wiring procedures.
- Avoid looking directly into lamp when illuminated.
- Ensure all mounts are securely attached and will support the weight of the fixture. Failure to properly support fixture may result in damage or injury, for which the manufacturer does not assume responsibility.

Specifications

Environmental Specifications	
Operating Temperature	-40°–122° F (-40°–50° C)
IP Rating	IP69K

Check product label for specific electrical specifications related to installation. Improper installation will void warranty.

Wiring Diagram



Installation (hanging)

1. Install eye bolt and lock into place with set screw.
2. Hang light on existing/pre-installed hook.
3. Attach safety cable to a secure support structure.
4. With supply power off, connect wiring.

